REMARKS

The original specification omitted reference to Figures 6a and 6b, and the Examiner noted that the element ROW0 was not found in Figure 6a. The specification has been amended to show that ROW0 is on Fig. 6b, and the Examiner should note that ROW0 is an input to the active data tap on Fig. 6b. It is believed this traverses the Examiner's objection to the drawings and allowance for issue of a patent is respectfully requested.

This response was unintentionally late and the application unintentionally abandoned. The appropriate fee and petition to revive the application are enclosed.

Conclusion

All grounds of rejection and/or objection are traversed or accommodated, and favorable reconsideration and allowance are respectfully requested.

January 9, 2008

Respectfully submitted,

Thelala Pina

Malcolm Pipes, Reg. No. 46,995 Attorney for Applicant

Customer Number 29106

Groover & Associates PO Box 802889 Dallas, TX 75380

Tel: 972-980-5840 Fax: 972-980 -5841